


FIG. 1








FIG. 2A

WALKER ET AL.	ATTORNEY DOCKET NO.: 04-027	




FIG. 2B

+

WALKER ET AL.	ATTORNEY DOCKET NO.: 04-027




FIG. 2C

WALKER ET AL.		ATTORNEY DOCKET NO.: 04-027
	,	




FIG. 3

WALKER ET AL.	ATTORNEY DOCKET NO.: 04-027



TRANSACTION IDENTIFIER	TRANSACTION DATE	TRANSACTION TIME	PRODUCT(S) PURCHASED	TRANSACTION TOTAL	÷	$\left( \right)$
T-987654321	3/5/2003	11:00 AM	A1, B3	\$1.50		${}$
T-876543219	3/5/2003	11:38 AM	. A3	\$0.50		${}$
T-765432198	3/5/2003	2:14 PM	B2, B3	\$1.25		${}$
T-654321987	3/6/2003	7:43 AM	. C3	\$1.00		${}$
T-543219876	3/6/2003	9:10 AM	C1	\$0.65		${}$
T-432198765	3/6/2003	3:05 PM	С3	\$1.00		(

FIG. 4A

WALKER ET AL.	ATTORNEY DOCKET NO.: 04-027

120 (CONT.)

	AMOUNT TENDERED	CHANGE DISPENSED
	\$2.00	\$0.50
	\$1.00	\$0.50
	\$2.50	\$0.75
$\setminus$	\$1.00	\$0
$\setminus$	\$1.00	\$0.35
	\$1.00	\$0 <sup>-</sup>

FIG. 4B

WALKER ET AL.	ATTORNEY DOCKET NO.:04-027

125

PRODUCT IDENTIFIER	PRODUCT DESCRIPTION	PRODUCT CATEGORY	ROW POSITION	RETAIL PRICE	
P-123456789	SNICKERS	CANDY	A1	\$0.75	
P-234567891	MILKY WAY	CANDY	A2	\$0.50	5
P-345678912	M&MS	CANDY	А3	\$0.50	5
P-456789123	LAYS	CHIPS	B1	\$0.75	5
P-567891234	DORITOS	CHIPS	B2 .	\$0.50	5
P-678912345	CHEETOS	CHIPS	B3	\$0.75	
P-789123456	SODA X	SODA	C1	\$0.65	5
P-891234567	SODA Y	SODA	C2	\$0.65	5
P-912345678	SODA Z	SODA	С3	\$1.00	

FIG. 5A

WALKER ET AL. ATT	ORNEY DOCKET NO.: 04-027

125 (CONT.)—

	MINIMUM SELLING PRICE	COST	ACTUAL (CURRENT) PRODUCT VELOCITY	IDEAL PRODUCT VELOCITY	CURRENT NUMBER IN STOCK
	\$0.40	\$0.20	0.5 / DAY	3.0 / DAY	5
5	\$0.40	\$0.20	0 / DAY	3.0 / DAY	4
	\$0.35	\$0.25	0.5 / DAY	4.0 / DAY	3 ·
	\$0.35	\$0.20	0 / DAY	3.0 / DAY	6
5	. \$0.25	\$0.20	0.5 / DAY	2.0 / DAY	4
5	\$0.35	\$0.27	1.0 / DAY	2.0 / DAY	5
5	\$0.50	\$0.25	0.5 / DAY	3.0 / DAY	4
$\int$	\$0.50	\$0.20	0 / DAY	2.0 / DAY	2
$\int_{-1}^{\infty}$	\$0.75	\$0.30	1.0 / DAY	3.0 / DAY	2

FIG. 5B

WALKER ET AL.	ATTORNEY DOCKET NO.: 04-027

130 —

COIN DENOMINATION	QUANŤITY
\$1.00	2
\$0.50	0
\$0.25	2
\$0.10	7
\$0.05	. 4
\$0.01	. 0

FIG. 6

WALKER ET AL.	ATTORNEY DOCKET NO.: 04-027
	<u></u>

135 —

CONDITION	RESOLUTION
IF PRODUCT JAM; AND AVERAGE ACTUAL ITEM VELOCITY FOR OTHER PRODUCTS IN SAME CATEGORY MEETS OR EXCEEDS AVERAGE IDEAL ITEM VELOCITY FOR OTHER PRODUCTS IN SAME CATEGORY; AND COIN INVENTORY (LESS DEPOSIT AMOUNT) EXCEEDS ANTICIPATED AMOUNT NEEDED TO MAKE CHANGE FOR FUTURE CUSTOMERS WITHIN FILL PERIOD	THEN COIN REFUND
IF PRODUCT JAM; AND AVERAGE ACTUAL ITEM VELOCITY FOR OTHER PRODUCTS IN SAME CATEGORY IS LESS THAN AVERAGE IDEAL ITEM VELOCITY FOR OTHER PRODUCTS IN SAME CATEGORY; AND COIN INVENTORY (LESS DEPOSIT AMOUNT) IS LESS THAN ANTICIPATED AMOUNT NEEDED TO MAKE CHANGE FOR FUTURE CUSTOMERS WITHIN FILL PERIOD	THEN SUBSTITUTE PRODUCT OFFER, WHERE PRODUCT IS FROM SAME CATEGORY AS INITIALLY REQUESTED PRODUCT

FIG. 7

140 -

CUSTOMER SERVICE ISSUE IDENTIFIER	DESCRIPTION OF CUSTOMER SERVICE ISSUE (DIAGNOSTIC DATA, ETC)	VALIDATED BY OPERATOR ?	RESOLUTION	RESOLUTION REDEEMED?
BILL@XYZ.COM	CUSTOMER STATES SNICKERS DID NOT VEND; ROW A1 SENSOR FIRED; DELIVERY BIN SENSOR DID NOT FIRE	YES	\$2.00 IN MACHINE CREDIT; COMPENSATION CODE = 183756	NO

WALKER ET AL	ATTORNEY DOCKET NO.: 04-027





FIG. 9






FIG. 10